Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 2/3/2016, 2/4/2016	Man Days: 2
Inspection Unit: Jerseyville/Virden	
Location of Audit: Jerseyville	
Exit Meeting Contact: Chris Juliusson	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Chris Juliusson	Quality Assurance	

Gas System Operations	Status
Gas Transporter	Panhandle Eastern
Annual Report (Form 7100.1-1) reviewed for the year:	Not Checked
General Comment:	•
The annual report will be reviewed in the Pawnee Training Center.	
Unaccounted for Gas	Not Checked
General Comment:	•
Unaccounted gas will be reviewed in the Pawnee Training Center.	
Number of Services	Not Checked
General Comment:	•

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

This will be reviewed at the Pawnee Training Center at a late	r.	
Miles of Main		Not Checked
General Comment:		
This will be reviewed at the Pawnee Training Center at a late	r.	
Is the operator maintaining documentation verifyi	ng their Maximum Allowable Operating Pressure(s)? (MAOP)	Satisfactory
General Comment:		
Regulator station inspection have the MAOP's on them, with	the MAOP'S being various in the Jerseyville operating center.	
Operating Pressure (Feeder)		Various
Operating Pressure (Town)		Various
Operating Pressure (Other)		Various
MAOP (Feeder)		Various
MAOP (Town)		Various
MAOP (Other)		Various
Does the operator have any transmission pipeline	es?	No
General Comment:		
No transmission lines in the Jerseyville operating center.		
Regulatory	y Reporting Records	Status
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Checked
General Comment:		
Telephonic notices records are in the Pawnee Training Center	er.	
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Checked
General Comment:		
Dot incident records are in the Pawnee Training Center.		
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Checked
General Comment:		
Supplemental incident records are in the Pawnee Training Ce	enter.	
Did the operator have any plastic pipe failures in	the past calendar year?	Not Applicable
General Comment:		
No plastic pipe failures in 2014 in the Jerseyville Operating C	enter.	

AMEREN ILLINOIS COMPANY/2-4-2016

Page 2 of 14

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Did the operator report Safety Related Conditions?	
Did the operator report Safety Related Conditions?	
	Not Checked
Fraining Center.	
Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Checked
Fraining Center.	
Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Not Checked
cords will be inspected in the Pawnee Training Center.	
ST REQUIREMENTS	Status
Are pressure test records being maintained for piping operating above 100 psig?	Satisfactory
sig was for farm taps and met the requirements.	
Are pressure test records being maintained for at least 5 years on piping operating below 100 psig?	Satisfactory
•	
pressure test.	
Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
<u> </u>	
temporarily disconnected it was retested from the disconnect to the meter set.	
UPRATING	Status
center.	
	within 5 working days of determination, but not later than 10 working days after discovery? Fraining Center. Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location? cords will be inspected in the Pawnee Training Center. ST REQUIREMENTS Are pressure test records being maintained for piping operating above 100 psig? sig was for farm taps and met the requirements. Are pressure test records being maintained for at least 5 years on piping operating below 100 psig? pressure test. Were service lines temporarily disconnected from the main properly tested prior to reconnection?

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
	OPERATIONS	Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Not Checked
General Comment:		
The Operations and Maintenance Manual review	is in the Pawnee Operating Center, and will be inspected at a later date.	
Has the operator conducted a review of	the Operator Qualification Plan once per yr/15 months?	Not Checked
General Comment:		
The Operator Qualification plan review is in the P	awnee Operating Center, and will be inspected at a later date	
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Not Checked
General Comment:	<u> </u>	•
Records associated to construction, operating his	story and maps, are in the mobile data terminal and operating personnel can obtain them t	there.
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Not Checked
General Comment:		
These records are in the Pawnee Operating Cent	der.	
CONTINU	UING SURVEILLANCE RECORDS	Status
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Not Checked
General Comment:		
These records are in the Decatur Plaza.		
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment:	•	-
Jerseyville Operating Center has no cast iron in t	he gas system.	
· -		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.603(b)][192.755]	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	Not Applicable
General Comment:		
Jerseyville Operating Center has no cast iron ir	n the gas system.	
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:	•	
Jerseyville Operating Center has no cast iron ir	n the gas system.	
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:	•	
Jerseyville Operating Center has no cast iron ir	n the gas system.	
DAM	MAGE PREVENTION RECORDS	Status
Category Comment:		
These records will be reviewed in the Pawnee	Training Center, at a later date.	
[192.603(b)][191.11(a)]	Did the operator track the number of damages per 1000 locate requests for the previous years?	Not Checked
Has the number of damages increase	d or decreased from prior year?	Not Checked
[192.603(b)][192.617]	Does the operator track records of accidents due to excavation damage to ensure causes of failures are addressed to minimize the recurrence?	Not Checked
[192.603(b)][192.614(c)(3)]	Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and the availability and use of the one call system?	Not Checked
Does the operator have a Quality Ass facilities?	urance Program in place for monitoring the locating and marking of	Not Checked
Do pipeline operators include perform	ance measures in facility locating contracts?	Not Checked
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of	
[IE ADIVI. 00.203.100(b)(1)]	gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Checked
. , , , , ,	gas reported to ICC JULIE Enforcement?	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	EMERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
General Comment:	·	
Supervisors are furnished copies of the latest edit	ition of the emergency plan, and they can be found electronically on computer or hard copy	<i>⁄</i> .
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Not Checked
General Comment:	·	
These records are in the Pawnee Training Center	r.	
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Not Checked
General Comment:	·	
These records are in the Pawnee Training Center	r.	
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Not Checked
General Comment:		
These records are in the Pawnee Training Center	r.	
[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Not Checked
General Comment:		
These records are in the Pawnee Training Cente	r.	
	ODORIZATION OF GAS	Status
[192.603(b)][192.625(f)]	Has the operator maintained documentation of odorant concentration level testing using an instrument?	Satisfactory
General Comment:	·	
Odorant reading were inspected for the years of	2013 & 2014 on GCS till November of 2014 and then the records went to Maximo.	
[192.603(b)][192.625(e)]	Has the operator maintained documentation of odorizer tank levels?	Satisfactory
General Comment:		
Tank reading were inspected for the years of 207	13 & 2014 on GCS till November of 2014 and then the records went to Maximo.	

AMEREN ILLINOIS COMPANY/2-4-2016

Page 6 of 14

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.603(b)][192.625(f)(1)]	Are master meter operators receiving written verification of odorant concentration levels from their gas supplier?	Not Applicable
General Comment:		
Ameren Illinois is not a master meter operator.		
[192.603(b)][192.625(f)(2)]	Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Not Applicable
General Comment:		
Ameren Illinois is not a master meter operator.		
PATRO	OLLING & LEAKAGE SURVEY	Status
[192.603(b)][192.721(b)(1)]	Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Not Applicable
General Comment:		
Jerseyville Operating Center did not have any main leakage.	ns in places or on structures where anticipated physical movement or external loading co	uld cause failure or
[192.603(b)][192.721(b)(2)]	Is the operator patrolling outside business districts at a minimum of 2 per year/7 1/2 months?	Satisfactory
General Comment:		
Jerseyville has 8 patrols that were inspected for th	e years of 2013 and 2014.	
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Satisfactory
General Comment:		
Staff inspected paper records for the year 2014, w.	ith the business district surveys being completed in the required timeframe.	
[192.603(b)][192.723(b)(2)]	Is the operator performing leakage surveys outside a business district at a minimum of every 5 years/63 months? Is the operator performing leakage surveys on cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the operator has yard lines then are those being surveyed?	Satisfactory
General Comment:		
Outside of the business district surveys for the year	or of 2014 were completed in the required timeframe.	
YA	RD LINES - RESIDENTIAL	Status
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located more than 3 feet away from the wall of a residence?	Satisfactory
General Comment:		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Ameren has documented the location where the meter is local	ated 3 feet away from the wall of a residence.	
[192.463,220 ILCS 2.2.03][220 ILCS 2.2.03]	Has the operator determined if cathodic protection is required on these services?	Not Applicable
General Comment:	·	
Ameren does not provide cathodic protection after the meter.		
[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection requirements, has the operator surveyed each line within the required leakage survey intervals?	Satisfactory
General Comment:		
Ameren surveyed these yard lines every three years.		
ABANDONMENT or DEACTI	VATION of FACILITIES PROCEDURES	Status
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Not Applicable
General Comment:	·	
Ameren Jerseyville did not have any abandoned pipe in the g	gas system in 2014.	
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Not Applicable
General Comment:		•
Ameren Jerseyville did not have any abandoned pipe in the o	gas system in 2014.	
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Satisfactory
General Comment:		•
Disconnects are on OAS computer system.		
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Not Applicable
General Comment:	•	•
Ameren Jerseyville did not have any abandoned pipe in the g	gas system in 2014.	
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Ameren Jerseyville did not have any abandoned p	pipe that crosses over or under a navigable waterway in the gas system in 2014.	
PRESSU	RE LIMITING AND REGULATION	Status
[192.603(b)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Regulator station inspections are on GCS till Nove	ember of 2014, and they then went to Maximo computer system.	
[192.603(b)][192.743(a)]	Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Records were inspected on GCS till November 20	14, then records went on a new computer system called Maximo for the remainder of the	year and the future.
[192.603(b)][192.743(b)]	If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Calculations are completed every year on GCS in	2014 till November, and then went on the new system called Maximo.	
[192.603(b)][192.741(a),192.741(b)]	Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district?	Satisfactory
General Comment:		
These records are on the scada system, and mon	itored by gas control.	
[192.603(b)][192.741(c)]	If there were indications of abnormally high- or low- pressure, were actions taken to correct any unsatisfactory operating conditions?	Not Applicable
General Comment:	1 .	
No high or low pressure indications in 2014.		
[192.603(b)][192.743(a),192.743(b),192.	.195(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point?	Not Applicable
General Comment:	·	
The Jerseyville line is being protected at this time and will be in operation by September of 2016.	by Panhandle Eastern Pipeline, Ameren will be installing their overpressure valve at the I	Manchester take point
[192.603(b)][192.743(a)]	If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Documentation is through the engineering evaluation	on that was completed in 9-19-2014.	
,	VALVE MAINTENANCE	Status
[192.603(b)][192.747(a),192.747(b)]	Did the operator inspect and maintain distribution valves necessary for the safe operation of the system at a minimum of 1 per year/15 months?	Satisfactory
General Comment:	·	
Valves were inspected for the year of 2014 on GCS	S, these records are on GCS till November 2014 and then records went on Maximo new	computer system.
[192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable
General Comment:	·	
No vaults in the gas system in Jerseyville.		
li	nvestigation Of Failures	Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Not Applicable
General Comment:		
No failures requiring analysis in the Jerseyville Ope	prating Contar for the year of 2014	
The familiar of forgaming arrangers in the decestions of	Grating Center for the year of 2014.	
	ELDING OF STEEL PIPE	Status
	· ·	Status
W	ELDING OF STEEL PIPE	Status
Category Comment:	ELDING OF STEEL PIPE	Status Not Checked
Category Comment: Welding records are in the Decatur Training Center	TELDING OF STEEL PIPE T. Does the operator have documentation for their qualified	
Category Comment: Welding records are in the Decatur Training Center [192.603(b)][192.225(b)]	Does the operator have documentation for their qualified welding procedure? Does the operator have documentation of welder	Not Checked
Category Comment: Welding records are in the Decatur Training Center [192.603(b)][192.225(b)] [192.603(b)][192.227,192.229]	Does the operator have documentation for their qualified welding procedure? Does the operator have documentation of welder qualification as required? Does the operator have documentation of welder OQ	Not Checked
Category Comment: Welding records are in the Decatur Training Center [192.603(b)][192.225(b)] [192.603(b)][192.227,192.229] [192.807]	Does the operator have documentation for their qualified welding procedure? Does the operator have documentation of welder qualification as required? Does the operator have documentation of welder OQ records? Does the operator have documentation of NDT personnel	Not Checked Not Checked Not Checked
Category Comment: Welding records are in the Decatur Training Center [192.603(b)][192.225(b)] [192.603(b)][192.227,192.229] [192.807] [192.709][192.243(b)(2)] [192.709][192.243(f)]	Does the operator have documentation for their qualified welding procedure? Does the operator have documentation of welder qualification as required? Does the operator have documentation of welder OQ records? Does the operator have documentation of NDT personnel qualification as required? Does the operator have documentation of NDT testing	Not Checked Not Checked Not Checked
Category Comment: Welding records are in the Decatur Training Center [192.603(b)][192.225(b)] [192.603(b)][192.227,192.229] [192.807] [192.709][192.243(b)(2)] [192.709][192.243(f)]	Does the operator have documentation for their qualified welding procedure? Does the operator have documentation of welder qualification as required? Does the operator have documentation of welder OQ records? Does the operator have documentation of NDT personnel qualification as required? Does the operator have documentation of NDT testing performed?	Not Checked Not Checked Not Checked Not Checked Not Checked
Category Comment: Welding records are in the Decatur Training Center [192.603(b)][192.225(b)] [192.603(b)][192.227,192.229] [192.807] [192.709][192.243(b)(2)] [192.709][192.243(f)] JOINING OF	Does the operator have documentation for their qualified welding procedure? Does the operator have documentation of welder qualification as required? Does the operator have documentation of welder OQ records? Does the operator have documentation of NDT personnel qualification as required? Does the operator have documentation of NDT testing performed? MATERIAL OTHER THAN WELDING	Not Checked Not Checked Not Checked Not Checked Not Checked

AMEREN ILLINOIS COMPANY/2-4-2016

Page 10 of 14

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Not Checked
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Not Checked
CORROSION CONTROL RECORDS		
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Satisfactory
General Comment:	·	
Maps are in G-Tech and GCS for cathodic prot	ection.	
[192.491][192.459]	Has the operator maintained documentation of an examination when buried pipe was exposed?	Satisfactory
General Comment:		
Ameren Jerseyville has documentation of pipe	examination when buried pipe is exposed.	
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
General Comment:		
Isolated sections of mains and services are bei	ing checked on a 10 percent annual readings.	
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory
General Comment:		
Rectifiers are being read 5 times a year.		
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
No critical or non-critical bonds in the gas syste	em.	
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Satisfactory
General Comment:		
Remedial actions are being taken on deficienci	ies indicated by monitoring of the readings.	
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	years/39 months?	
General Comment:		
No unprotected piping it the Jerseyville Operating Center.		
[192.491][192.467(a),192.467(c),192.467(d)]	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Satisfactory
General Comment:	<u> </u>	•
Casings are being inspected each year.		
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
General Comment:		
The Jerseyville Operating Center believes they have a sufficient	cient number of test stations.	
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Satisfactory
General Comment:	<u> </u>	•
All test leads are electrically conductive in the system.		
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Satisfactory
General Comment:		<u> </u>
Documentation shows that cathodic protection is no affecting	ng adjacent underground metallic structures.	
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Not Applicable
General Comment:	•	
Ameren Jerseyville has no corrosive gas in the gas system.		
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Not Applicable
General Comment:	•	
Jerseyville did not remove any pipe in 2014.		
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

No coupon monitoring was conducted in the Jerseyville Op	erating Center in 2014.	
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory
General Comment:		
Atmospheric corrosion monitoring is done on a four year su	rvey along with the leak surveys.	
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory
General Comment:		
Documentation of atmospheric is entered on GCS complian	nce system.	
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Not Applicable
General Comment:	•	
No pipe was removed in the Jerseyville Operating Center in	2014.	
TRAINING - 83 IL ADM. CODE 520		Status
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Not Checked
General Comment:	•	
Training records are being maintained in the Pawnee Opera	ating Center.	
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Not Checked
General Comment:		
Training records are being maintained in the Pawnee Opera	ating Center.	
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Applicable
General Comment:		
Ameren Illinois is not a municipal operator.		
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Satisfactory
General Comment:		
Procedures are updated periodically and are in the O&M m	anual.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

AMEREN ILLINOIS COMPANY/2-4-2016 Page 14 of 14